

ATT VII



**PHOTOGRAPHY LOG
LEAVENWORTH HATCHERY
LEAVENWORTH, WASHINGTON**

Photographs 1 - 3 taken by Eileen Hileman on September 18, 2001, at Leavenworth Hatchery, Leavenworth, Washington. Photographs 1 - 3 show nursery in the Hatch Building.



Photograph 4 taken by Eileen Hileman on September 18, 2001, at Leavenworth Hatchery, Leavenworth, Washington. Photograph 4 shows an incubator in the nursery in the Hatch Building.

Leavenworth Hatching
AGFA
PAPER
very,



Photograph 4 taken by Eileen Hileman on September 18, 2001, at Leavenworth Hatchery, Leavenworth, Washington. Photograph 4 shows an incubator in the nursery in the Hatch Building.


Leavenworth Hatchery

Speshtige
PAPER


ery,



Photograph 4 taken by Eileen Hileman on September 18, 2001, at Leavenworth Hatchery, Leavenworth, Washington. Photograph 4 shows an incubator in the nursery in the Hatch Building.




ery,




Photograph 4 taken by Eileen Hileman on September 18, 2001, at Leavenworth Hatchery, Leavenworth, Washington. Photograph 4 shows an incubator in the nursery in the Hatch Building.

Photographs 5 and 6 taken by Eileen Hileman on September 18, 2001, at Leavenworth Hatchery, Leavenworth, Washington. Photographs 5 and 6 show the old abandoned in place raceways.




Photograph 7 taken by Eileen Hileman on September 18, 2001, at Leavenworth Hatchery, Leavenworth, Washington. Photograph 7 shows the raceways built in 1998.




Photograph 7 taken by Eileen Hileman on September 18, 2001, at Leavenworth Hatchery, Leavenworth, Washington. Photograph 7 shows the raceways built in 1998.

Photograph
Leavenwor



Photograph 7 taken by Eileen Hileman on September 18, 2001, at Leavenworth Hatchery, Leavenworth, Washington. Photograph 7 shows the raceways built in 1998.

Photographs 8 and 9 taken by Eileen Hileman on September 18, 2001, at Leavenworth Hatchery, Leavenworth, Washington. Photographs 8 and 9 show the raceways that were built in 1979.




Photographs 10 and 11 taken by Eileen Hileman on September 18, 2001, at Leavenworth Hatchery, Leavenworth, Washington. Photographs 10 and 11 show the sand trap filter system and the sand piles that have been removed from the trap during the cleaning process.

Leavenworth
Hatchery

Leavenworth
Hatchery,
9.


AGF



Photographs 10 and 11 taken by Eileen Hileman on September 18, 2001, at Leavenworth Hatchery, Leavenworth, Washington. Photographs 10 and 11 show the sand trap filter system and the sand piles that have been removed from the trap during the cleaning process.



Photographs 10 and 11 taken by Eileen Hileman on September 18, 2001, at Leavenworth Hatchery, Leavenworth, Washington. Photographs 10 and 11 show the sand trap filter system and the sand piles that have been removed from the trap during the cleaning process.



Photographs 10 and 11 taken by Eileen Hileman on September 18, 2001, at Leavenworth Hatchery, Leavenworth, Washington. Photographs 10 and 11 show the sand trap filter system and the sand piles that have been removed from the trap during the cleaning process.

Photograph 12 taken by Eileen Hileman on September 18, 2001, at Leavenworth Hatchery, Leavenworth, Washington. Photograph 12 shows the two adult holding ponds. The ponds were empty at the time of the inspection.



Photograph 13 taken by Eileen Hileman on September 18, 2001, at Leavenworth Hatchery, Leavenworth, Washington. Photograph 13 shows the outfall at the fish ladder.

Photographs 14 and 15 taken by Eileen Hileman on September 18, 2001, at Leavenworth Hatchery, Leavenworth, Washington. Photograph 14 shows the pollution abatement pond. Photograph 15 shows the amount of sand removed from the pond in the last cleaning in 1998.



Photographs 16 and 17 taken by Eileen Hileman on September 18, 2001, at Leavenworth Hatchery, Leavenworth, Washington. Photograph 16 shows the discharge from the abatement pond into the canal or pipe. Photograph 17 shows the canal/pipe discharging into Icicle Creek.

Pho
Ha
Pho

AGFA
PAPER
PAPER
PAPER


AGFA
PAPER
PAPER
PAPER

3.




Photographs 16 and 17 taken by Eileen Hileman on September 18, 2001, at Leavenworth Hatchery, Leavenworth, Washington. Photograph 16 shows the discharge from the abatement pond into the canal or pipe. Photograph 17 shows the canal/pipe discharging into Icicle Creek.

Ph
Ha
Ph



Photographs 16 and 17 taken by Eileen Hileman on September 18, 2001, at Leavenworth Hatchery, Leavenworth, Washington. Photograph 16 shows the discharge from the abatement pond into the canal or pipe. Photograph 17 shows the canal/pipe discharging into Icicle Creek.



Photographs 16 and 17 taken by Eileen Hileman on September 18, 2001, at Leavenworth Hatchery, Leavenworth, Washington. Photograph 16 shows the discharge from the abatement pond into the canal or pipe. Photograph 17 shows the canal/pipe discharging into Icicle Creek.